



30/2-30/3	G	G1	G2	F	F1	F2	F3	F4	H
/2...71 B5 /2F...71 B5	14	16,3	5	160	130	110	10	9	315
/2...80 B5 /2F...80 B5	19	21,8	6	200	165	130	11	11	309
/2...90 B5 /2F...90 B5	24	27,3	8	200	165	130	11	11	309
/2...100-112 B5 /2F...100-112 B5	28	31,3	8	250	215	180	12	13	312
/3...56 B5 /3F...56 B5	9	10,4	3	120	100	80	8	7	303
/3...63 B5 /3F...63 B5	11	12,8	4	140	115	95	12	9	302
/3...71 B5 /3F...71 B5	14	16,3	5	160	130	110	10,5	9	301
/3...80 B5 /3F...80 B5	19	21,8	6	200	165	130	10,5	11	301

P = 160						
N	C	M	P	S	S1	U
110	65	130	160	10	3,5	9

P = 200						
N	C	M	P	S	S1	U
130	65	165	200	10	3,5	11,5

P = 250						
N	C	M	P	S	S1	U
180	65	215	250	12	4	14

P = 250						
N	C	M	P	S	S1	U
180	80	215	250	10	4	14