



60/2-60/3	G	G1	G2	F	F1	F2	F3	F4	H
/2...100-112 B5	28	31,3	8	250	215	180	25	M12	551
/2F...100-112 B5									
/2...132 B5	38	41,3	10	300	265	230	25	M12	551
/2F...132 B5									
/2...160 B5	42	45,3	12	350	300	250	25	17	551
/2F...160 B5									
/2...180 B5	48	51,8	14	350	300	250	25	17	551
/2F...180 B5									
/2...200 B5	55	59,3	16	400	350	300	25	18	551
/2F...200 B5									
/3...80 B5	19	21,8	6	200	165	130	15	11,5	534
/3F...80 B5									
/3...90 B5	24	27,3	8	200	165	130	15	11,5	534
/3F...90 B5									
/3...100-112 B5	28	31,3	8	250	215	180	15	14	537
/3F...100-112 B5									
/3...132 B5	38	41,3	10	300	265	230	15	14	537
/3F...132 B5									

P = 350						
N	C	M	P	S	S1	U/n°
250	130	300	350	18	5	18/4

450						
N	C	M	P	S	S1	U/n°
350	190	400	450	18	5	18/8