



25/2-25/3	G	G1	G2	F	F1	F2	F3	F4	H	H1
/2....63 B5 /2F....63 B5	11	12,5	4	140	115	95	12	9	268	287
/2....71 B5 /2F....71 B5	14	16,3	5	160	130	110	10	9	273	292
/2....80 B5 /2F....80 B5	19	21,8	6	200	165	130	11	11	267	286
/2....90 B5 /2F....90 B5	24	27,3	8	200	165	130	11	11	267	286
/2....100-112 B5 /2F....100-112 B5	28	31,3	8	250	215	180	12	13	270	289
/3....56 B5 /3F....56 B5	9	10,4	3	120	100	80	8	7	269	288
/3....63 B5 /3F....63 B5	11	12,8	4	140	115	95	12	9	259,5	278,5
/3....71 B5 /3F....71 B5	14	16,3	5	160	130	110	10,5	9	258,5	277,5

P = 120							
N	C	M	P	α	S	S1	U
80	55	100	120	45°	8	3,5	6,5

P = 160							
N	C	M	P	α	S	S1	U
110	55	130	160	45°	9	9,5	9

P = 200							
N	C	M	P	α	S	S1	U
130	50	165	200	58°	10	4	11

P = 200							
N	C	M	P	α	S	S1	U
130	85	165	200	58°	10	4	11